MARYLAND INVENTORY OF HISTORIC PROPERTIES

Maryland Historical Trust HISTORIC PROPERTIES
State Historic Sites Inventory Form

Survey No. B-4374

Magi No.

DOE _yes _no

1.	Nam	e (indicate preferred name)	
histo	ric	728-730 North Howard Street	
and/c	or common	Atlas Health Inc.	
	Loca	tion	
stree	t & number	728-730 N. Howard Street	not for publication
city,	town	Baltimore vicinity of congressional district	Seventh
state	0 0	Maryland Baltimor	re
3.	Clas	sification	
x_	egory district building(s) structure site object	Ownership Status Present Use public	museum park private residence religious scientific transportation other:
4.	Own	er of Property (give names and mailing address	es of <u>all</u> owners)
name	,	Raymond Ellison	
stree	t & number	7501 Park Heights Avenue telephone	
city,	town	Baltimore MD state and zip code	21208
5.	Loca	tion of Legal Description	
court	thouse, regis	try of deedsBeadtimore City Courthouse	1iBHB3437
stree	t & number	100 N. Calvert Street, Room 610	folid12
city, 1	town	Baltimore state	MD
6.	Repr	esentation in Existing Historical Sur	veys
title			
date		federal st	ate county loc
)0:	sitory for su	vey records	
city t		state	

7. Description

Survey No. B-4374

Condition

___ excellent
___ good ___ ruins ___ altered ___ unexposed

Check one
___ unaltered ___ original site
___ moved date of move ______

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

Resource Count: 2

This circa 1830 Greek Revival building is a part of a series of rowhouses that extend north up the west side of North Howard Street. The two-and-one-half story brick building is laid in a variable American bond and has Greek Revival eyebrow windows in the attic story. The gable roof runs parallel to the street. This particular unit is four bays wide, but was originally two two-bay units, as evidenced in brick seams and the pattern of the row. It is now treated as one four-bay unit with a street frontage of 30'7" and a depth of 67'4". The building sits on the southwest corner of Howard and Madison streets; the main entrance now faces Madison Street.

The first story has been substantially altered. It is completely covered with stucco, except for a post-World War Two shallow projecting bay that is covered with mock wood panelling that has a small window. A modern awning runs around the first story of both the Howard and Madison streets facades.

The four second story windows have brick splayed jack arches. The first and second bays (to the south) have 2/2 sash and the third and fourth bays (to the north) have 6/2 sash. All four attic story eyebrow windows are two-light casements. The cornice is a two brick corbelled cornice. The gable roof is slightly hipped on the Howard Street side.

The north wall faces Madison Street and is eight bays long. The first story is completely altered and the original fabric is obscured by wall boarding; the upper stories are historically intact. The first six bays appear to be original to the building. The first six bays run the full two-and-one-half-story height and the fenestration pattern with splayed jack arches, eyebrow windows and two brick corbelled cornice continues the pattern from the facade. (The pattern of a two-bay deep main house and four-bay deep back building corresponds to the pattern found in the 720 N. Howard unit of the rowhouses.) The seventh bay is only two stories and has a different type of jack arch and a plain cornice, indicating a different date of construction. The eighth bay is a recent frame addition covered with asbestos shingles. Chimneys pierce the roof line over the fourth and sixth bays.

The west wall of the back building reveals that the extension is two bays wide. It is covered by half-gable roof.

1400 1500 1600 1700	1599 agriculture 1699 architecture 1799 art 1899 commerce	oric .		munite servation cation neerin oration	y plannir ion s g n/settlen	ng	law liter mili mus phil	ature tary sic osophy	rchitecture	scie scul soci hum thea	nce pture al/ anitarian
Specific	dates		Builder/	Archi	tect un	kno	wn			30000	191911-1527
check:	Applicable Criteria: _	_A	B X	C	D				la besta	Lasting Control	
	Applicable Exception:	A	B	c	D	E	F	G		-	
	Level of Significance:	I	nationa	1 _	_state	x	local				
Prepare	both a summary paragrap	h o	f signi	Lfica	nce an	d a	gener	al sta	tement o	of histo	ory and

This building is part of the only remaining row of modest

Greek Revival speculative rowhouses on North Howard Street. The two-and one-half-story buildings with eyebrow windows in the attic story were not found in any other part of this surveyor's 120-

building survey of the Howard Street commercial district.

The size and massing of this two-bay unit is illustrative of early nineteenth-century real estate speculation. The construction of two-bay double houses was a common way of limiting the amount of financial risk to the speculative builder, since the amount of money invested was minimized by the relative smallness of the project. The small amount of space within these houses is also indicative of the status of the laboring class whose means, however modest, permitted them to purchase or at least rent single family homes.

The presence of dwellings, or possibly combination shophouses, in this block indicates the residential character of the neighborhood in the early nineteenth century. It is possible this building was originally a shop-house type. The first story would have been used for commercial purposes and the upper stories would have been used as dwelling quarters. Architectural historian Richard Longstreth writes that "the rapid growth of commerce and manufacturing after independence led to a proliferation of the shop-house form in both new buildings and existing ones altered so that their commercial purpose was clearly indicated on the exterior. Shop-houses prevailed in emerging commercial centers of cities and towns alike through the early decades of the 19th Examples can still be seen in areas that have not experienced radical change, even though the shopfronts themselves have almost always been altered. . . the upper section retaining a domestic character."1

¹ Longstreth, Buildings of Main Street, p. 24.

9. Major Bibliographical References

Survey No.B-437,4

Richard Longstreth, The Buildings of Main Street (Washington: Preservation Press, 1987).

10. G	eograph	ical Data			
Acreage of no Quadrangle n UTM Reference	ame	e East Quad	rences	Quadrang	gle scale
A Zone Ea	sting N	lorthing	BZone	Easting Easting	Northing
C			D F H		
Collection of Managements (1) (2) to collect 40 Luni	dary description	for properties over	lapping state or co	unty boundaries	s
List all state			lapping state or co	unty boundaries	s code
List all state		for properties over		unty boundaries	
List all state state state	es and counties	for properties over code	county	unty boundaries	code
List all state state state 11. Fo	es and counties	for properties over code code	county	unty boundaries	code
List all state state 11. Fo	es and counties	for properties over code code pared By Architecture	county		code
List all state state state	orm Prepois Diane Shaw,	for properties over code code pared By Architecture	county county al Historian date	te Decembei	code

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust

Shaw House

21 State Circle

Annapolis, Maryland 21401

(301) 269-2438

MARYLAND HISTORICAL TRUST
DHCP/DHCD
100 COMMUNITY PLACE
CROWNSVILLE, MD 21032-2023
301-514-7600

B-4374 728-730 North Howard Street Baltimore, MD Section 8 Significance 8.1

The first story was likely altered several times over the buildings 150 year life, particularly as the commercial use intensified. Nonetheless, the only existing first-story fabric is of recent date. The plate glass window, doors and mock wood siding are examples of the low-budget commercial remodellings that characterize Howard Street's recent architecture and indicates the relatively marginal nature of the contemporary commercial street.

The preservation of this building indicates the lessening real estate pressures on the upper stretches of North Howard Street during the nineteenth and early twentieth century, a period when much remodelling or rebuilding was undertaken. Longstreth continues, "the gradual abandonment of the shop-house as the dominant form of commercial architecture was due to the everincreasing demands for trade and professional services along with a corresponding increase in land values, all of which fostered the design of buildings used entirely for commercial purposes."2 turn-of-the-century remodelling of the first story may have saved the building, as it enhanced the commercial viability of the space. The survival of this building is rare within the Baltimore commercial district. The back building is still used for residential purposes.

Longstreth, <u>The Buildings of Main Street</u>, pp. 24,29.

COMPREHENSIVE PLAN DATA

HISTORIC CONTEXT:

Geographic Organization: Piedmont

Chronological/Developmental Period:

Agricultural-Industrial Transtition, 1815-1870 Modern Period, 1930-present

Historic Period Themes: Architecture Economics

Resource Type:
Building

Historic Environment: Urban

Historic Function and Use:

Residential-Commercial?

Known Design Source: None

SOURCES AND IS NOT AN AUTHENTIC SURVEY.



B-4374 728-730 N Howard St. Balhmore, MD Diane Shaw Maryland SHPO NEElevation



B-4374
728-730 N. Housed St.
Baltimore, MD
Diane Shaw
8/91
Maryland SHPO
East Elevation
2/2